

PICED 4.x Release Notes

C-BUS

Table of Contents

- PICED 4.13.2 1
 - Released 1
 - What’s New 1
 - Other Fixes 1
- PICED 4.13.1 2
 - Released 2
 - What’s New 2
 - Wiser 1.5 Firmware Update 2
 - Other Fixes 2
- PICED 4.13.0 3
 - Released 3
 - What’s New 3
 - Wiser 2 Support 3
 - Other Fixes 3

PICED 4.13.2

Released

September 2020

What's New

Maintenance release only.

Other Fixes

- SP-3822 – Fixed an issue with the DALI line mapping line being reset to line A when line B is selected and saved.
- SP-3835 – Fixed an issue with the webcam refresh rate being ignored.
- SP-3837 – Fixed an access violation when typing incorrect values in the Application field on the Scene Components tab of the Scene Editor window.

PICED 4.13.1

Released

May 2016

What's New

Wiser 1.5 Firmware Update

This release includes Wiser 1.5 firmware version 1.30.1. It addresses the following issues:

- ECHO-1146 – Daylight savings causes the schedules to be out by 1 hour when NTP is disabled.
- ECHO-1144 – IP address format error appears when changing the IP address from the router interface.

Other Fixes

- SP-2492 – Fixed issue with fonts missing from CTC project archive.
- SP-3113 – Updated public holiday templates.
- SP-3362 – Fixed issue with Name field covering buttons in Add Irrigation Program dialog.
- SP-3363 – Fixed issue with irrigation schedule not displaying when not controlling an irrigation zone.
- SP-3625 – Fixed an issue with the Maps Used field showing incorrect values in the DALI Mapping window.
- SP-3661 – Fixed an issue with the Maps Used field showing incorrect values in the DALI Mapping window.
- SP-3678 – Fixed an issue with the Toolkit project file being renamed by the archiving wizard.
- SP-3709 – Increased the maximum delay between irrigation zones.
- SP-3773 – Re-added missing Wiser 1.5 firmware.
- SP-3780 – Fixed an access violation when importing archive.
- SP-3781 – Fixed an access violation when selecting a profile for a component.
- SP-3806 – Enabled DALI UDP port to be shared with other applications.
- SP-3807 – Improved layout of DALI configuration fields in the Project Details wizard.
- SP-3808 – Enabled the DALI Site ID to be configured.

PICED 4.13.0

Released

February 2015

What's New

Wiser 2 Support

This release delivers improved support for the Wiser 2 unit.

Other Fixes

- SP-3708 – Fixed issue with Wiser projects where a HVAC widget could be created without a HVAC zone.
- SP-3718 – Fixed group status PFR data not being updated when refreshing Wiser project from unit.
- SP-3770 – Added warning when enabling Wi-Fi for a Wiser project.
- SP-3771 – Fixed an issue with remotely retrieving the project from a Wiser 2 unit.