DALIBuildings 2.2.0 Release Notes

December 2018

WHAT'S NEW

PRODUCT CHANGES

This build fixes the following issue:

1. The ballasts which did not have MAX set to 100% were failing the status test with the result of "Limit Reached".

Please note: this release would require upgrading the database.